

Date: Thursday, 4/12/2007 9:37:54 AM
 User: Kim Johnston

Process Sheet

Customer	: CU-DAR001, Dart Helicopters Services	Drawing Name	: LONG STEP ASSEMBLY HIGH SKID RH
Job Number	: 31798		
Estimate Number	: 10274		
P.O. Number	: N/A	Part Number	: D350591312
This Issue	: 4/12/2007	S.O. No.:	: N/A
Prsht Rev.	: NC	Drawing Number	: D3272 REV A
First Issue	: N/A	Project Number	: N/A
Previous Run	: 31765	Drawing Revision	: A
		Material	: N/A
		Due Date	: 5/30/2007
Written By	:	Qty:	10 Um: Each
Checked & Approved By	:		
Comment	: Est Rev:A 04.03.22 New issue KJ/RF		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



Comment: DOCUMENT CONTROL

Photocopy bluefile and type labels as per PPP D350-591-312 CHG001

2.0	D2622120C	Extrusion
-----	-----------	-----------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s)

Pick:

Qty	Part Number
1	D2622-120

Description	Batch
Extrusion	B30199X1 / B31984 X9

FF 07-05-23

3.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2622-120 extrusion to 116.25" long as per Dwg D3272 using cutting table setup DT 8185-2A

2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets.

3-Deburr

4.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

5.0	D30671	End Plate
-----	--------	-----------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s)

Pick:

Qty	Part Number
1	D3067-1

Description	Batch
End Plate	B31653

FF 07-06-06

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 4/12/2007 9:37:54 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 31798

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

D32191

Support



Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s)

Pick:

Qty Part Number

Description Batch

2 D3219-1

Support

331837=1

331640=19

PK 07-06-06 10

7.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel end for welding FWD ONLY

PK 07-06-06 10

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod M102756
M103317

PK 07-06-06 10

3-Grind End Plate flush

PK a.m 07-06-06 10

8.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

PK 07/06/06 10

9.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

PK 07-06-06 10

10.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

a.m 07-06-07 10

11.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

PK 07-06-07 10

12.0

D3065041

Step Leg Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3065-041

Step Leg Assy

B31294

PK a.m 07-06-07 10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 4/12/2007 9:37:54 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 31798

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

13.0

D30661

Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

2 D3066-1

Spacer

B31834

Ham

07.06.07

20

14.0

MS20600AD4W4

Rivets



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

16 MS20600AD4W4

Rivet

M104156

Ham

07.06.07

18

15.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Assemble Leg Assembly as per Dwg D3272.

Ham

07.06.07

Ham

10

16.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

2006-11

(U)

(R1)

17.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3067-1

End Plate

B31653

Ham

07.06.11

10

18.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel Aft end for welding

2-Inspect for foreign object as per QSI 024

3-Weld Aft End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod M102756

Ham

07.06.11

10

Ham

07.06.11

10

Ham

07.06.11

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 4/12/2007 9:37:54 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 31798

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

4-Grind End Plate flush

install rivet
1/4 in
07-06-12

19.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

07/06/12 *(10)* *RA*

20.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07-06-12 *(10)* *R14*

21.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Touch up Alodine

07-06-12 *(10)*

22.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

07-06-14 *(10)*
BR/

23.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3272 and QSI 005 4.4

07/06/15 *10*
FL

24.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: Inspect Powder Coat and Wing Walk

7/6/18 *(10)*

25.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

26.0

D22303

Mounting Lug



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 D2230-3 Mounting Lug

1330993 *7/6/18* *SP*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 4/12/2007 9:37:54 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 31798

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

27.0

D2618

Bushing



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2618

Bushing

B30465 X

28.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 6.0000 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2856-400-720 Abrasion Strip

B30822 X

29.0

D32351

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D3235-1

Mounting Lug

B30996 X

30.0

D3278041

Support Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D3278-041

Support Assembly

B31661 X

31.0

AN335A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN3-35A

Bolt

M104021 X

32.0

AN413A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 AN4-13A

Bolt

M104256 - M104118 - 7/6/1859
(14) X (66) X

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 4/12/2007 9:37:54 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 31798

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

33.0

AN536A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN5-36A

Bolt

M104322 X

34.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD10

Washer

710

M104118 X

35.0

AN960JD416

Washer



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

16 AN960JD416

Washer

710

M103691 X

36.0

AN960JD516

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD516

Washer

M103641 X

37.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L3

Nut (or -3)

710

M103691 X

7/16/18 SS9

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☐ No ☒ DQA: ☒ Date: 07/04/20
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 4/12/2007 9:37:54 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 31798

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

38.0

MS21042L4

Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 MS21042L4

Nut (or -4)

M102552 ✓

39.0

MS21042L5

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L5

Nut (or -5)

M102536 ✓

7/6/18 SP(10)

40.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

7/6/19 (10) 0207/06/19 (10)

41.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-591-312

Location:

REV-B *07/06/19* *(10)*

42.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

07/06/20

Job Completion



0207/06/20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>CP</i>	DRAWN BY <i>CP</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>#</i>	APPROVED <i>#</i>	DRAWING NO. D3272	REV. A SHEET 1 OF 2
DATE 04.03.01		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	

RELEASED
04.04.05 *#*

Part No.	Description	QTY -041	QTY -042
D3272-041	Step Assembly, High Long (LH)	X	
D3272-042	Step Assembly, High Long (RH)		X
D2622-120	STEP EXTRUSION	1	1
D3219-1	SUPPORT	2	2
D3065-041	LEG ASSEMBLY	1	1
D3066-1	SPACER	2	2
D3067-1	END PLATE	2	2
MS20600AD4W4	RIVET	16	16

GENERAL NOTES:

- 1) -041 SHOWN, FOR -042 INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. **31798**

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN	APPROVED	DRAWN BY	DART AEROSPACE LTD
CHECKED	APPROVED	DRAWING NO.	HAWKESBURY, ONTARIO, CANADA
DATE		TITLE	REV. A
04.03.01		STEP ASSEMBLY, HI LONG	SHEET 2 OF 2
			SCALE
			1:20



RELEASED

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WEEK ORDER
NO. 31798